

1 / 22




FIG. 1




FIG. 2

20250625001

2 / 22




FIG. 3




FIG. 4

2022-01-05 10:52:50

3 / 22




FIG. 5




FIG. 6

2025060106525001

4/22




FIG. 7




FIG. 8

5/22




FIG. 9

6 / 22




FIG. 10

7/22




FIG. 11

8 / 22




FIG. 12




FIG. 13

FIG. 12

9/22




FIG. 14




FIG. 15

202510-69225001

10/22




FIG. 16




FIG. 17

11/22




FIG. 18




FIG. 19

12 / 22




FIG. 20

13/22




FIG. 21

14/22




FIG. 22

15/22




FIG. 23

16/22




FIG. 24




FIG. 25

20250625001

17/22




FIG. 26




FIG. 27

18/22




FIG. 28




FIG. 29

Sheet 18 of 22

19/22




FIG. 30




FIG. 31

20 / 22





FIG. 32


21 / 22



PRIOR ART
FIG. 33

22 / 22

ELECTRIC FIELD INTERFERENCE FROM
THE ADJACENT SIGNAL LINE



PRIOR ART
FIG. 34